Office of the Inspector Chailengta Education Inspectorate (State) Chailengta, Longtharai Valley, Dhalai, Tripura

No.F. 1(31)-15-CLT/2012 8295

Date - 09/10/2020

Building Safety Certificate

This is to certify that the school building block consisting of six buildings of Chailengta Government English Medium H S School are all safe for use in all weathers for the students and the staff of that school.

To find out the safety measure, a team of my engineers have visited the institution on 01.10.2020 to enquire about the purpose. As per their findings, these buildings were built in the years ranging from 2006 to 2008. All these buildings are single storey buildings in nature and they have GI sheets for roofing and the walls are all pucca (brick walls).

3710/2020

(Paritosh Chandra Das) Inspector of Schools, Chailengta Education Inspectorate (State), Chailengta, LTV, Dhalai, Tripura

SRI PARITOSH CHANDRA DAS H.O & D.D.O. Chailengta Edn. Inspectorate (State) Chailengta, LTV. Dhalai Tripura D.D.O. Code-04014.